

Site	Inspection Date	Status	Notes
CHE - CZ 01	15-Aug-24	Operational	Replaced the float valve, blew out the lines and it is working fine. Left 1/2 of a block of salt.
CHE - CZ 02	15-Aug-24	Operational	swept the apron and put in a 275 gal load of water and left 1/2 of a block of salt.
CHE - CZ 03	25-Oct-24	Operational	
CHE - CZ 04	25-Oct-24	Operational	
CHE - CZ 05	25-Oct-24	Nonoperational	Something dug up the float box and tore it up. I shut the float box valve off so it would store water over winter. The float ball had holes punched into it so it wasn't usable. I didn't have a spare with me so repair will have to wait until spring.
CHE - CZ 06	25-Oct-24	Operational	
CHE - CZ 07	25-Oct-24	Operational	
CHE - CZ 08	25-Oct-24	Operational	
CHE - CZ 09	25-Oct-24	Operational	The tree that had the identification sign on it fell over so it will need a new sign.
CHE - CZ 10	29-Aug-24	Operational	Installed new drinker.
CHE - CZ 12	05-Aug-23	Operational	
CHE - CZ 13	25-Oct-24	Operational	Someone had removed the bear guard and reattached it so the measurement access hole didn't line up with the downspout on the gutter. Had to remove it and attach it correctly so I could measure the water level. I have a hard time understanding why someone would do that.
CHE - DL 06	06-Aug-24	Operational	has tree stand belonging to ODFW.
CHE - DL 07	18-Jul-24	Operational	Installed new identification sign.
CHE - DL 14	06-Aug-24	Operational	
CHE - DL 15	05-Aug-23	Operational	
CHE - DL 19	17-Sep-24	Operational	
CHE - DL 20	06-Aug-24	Operational	
CHE - DL 21	05-Aug-23	Operational	
CHE - DL 22	25-Oct-24	Operational	
CHE - DL 23	05-Aug-23	Operational	
CHE - DL 24	18-Jul-24	Operational	Operational 16" water. Installed new identification sign.  Has ODFW deer trap, needs new 2x6"s and 8 pieces of metal , lots of usage
CHE - DL 25	18-Jul-24	Operational	Installed new identification sign.
CHE - DL 26	05-Aug-23	Operational	

CHE - DL 27	18-Jul-24	Operational	People interfering with, turned valve off at drinker, I opened it, has hunters camera. Installed new identification sign.
CHE - DL 28	30-Jul-22	No Status	No access
CHE - DL 29	05-Aug-23	Operational	
CHE - DL 30	05-Aug-23	Operational	
CHE - DL 31	05-Aug-23	Operational	
CHE - DL 32	06-Aug-24	Operational	
CHE - DL 33	05-Aug-23	Operational	
CHE - DL 34	18-Jul-24	Operational	Salt was gone so replaced, good usage. Installed new identification sign.
CHE - DL 35	08-Nov-22	Operational	
CHE - DL 36	18-Jul-24	Operational	Apron can use repair. Installed new identification sign.
CHE - DL 37	08-Nov-22	Operational	
CHE - FS 03	29-Oct-24	Operational	
CHE - FS 04	29-Oct-24	Operational	
CHE - FS 05	29-Oct-24	Operational	
CHE - FS 09	29-Oct-24	Operational	
CHE - FS 10	29-Oct-24	Operational	
CHE - FS 11	29-Oct-24	Nonoperational	The Forest Service still hasn't burned the slash pile that is on top of the drinker and float box. They also bermed the road blocking access to the guzzler requiring a half mile hike to get to it. Not sure what the Forest Service is up to. Are they planning to abandon the guzzler?
CHE - FS 12	29-Oct-24	Nonoperational	The float box was dug up and the float ball was ripped off of the float valve arm. I turned off float box valve to collect water over the winter. It will need a new float ball next spring to get it back operational.
CHE - FS 13	29-Oct-24	Nonoperational	Someone had dug up the Float box and detached the Float arm/float ball from the float valve. The float box shut off valve is broken and needs replaced.
CHE - FS 18	29-Oct-24	Operational	
CHE - FS 38	25-Jun-24	Operational	it had a full salt block, we cleaned the apron and drinkers, it needs a sign. I will also send the report to Bend ODFW.
CHE - FS 39	28-Jun-24	Operational	Dug up float box and blew out line at float valve
CHE - FS 42	30-Jun-24	Operational	
CHE - FS 43	30-Jun-24	Operational	
CHE - FS 45	18-Jun-24	Limited	Cleaned but needs new metal, 3 2X6s and new screen over catch trough. Unplugged down spout.

CHE - FS 46		No Status	Can not locate
CHE - FS 48	28-Jun-24	Operational	
CHE - MODOC		No Status	
CHE - WC I	18-Jul-24	Operational	Float box was plugged, fixed. Has plastic float valve, should change. Installed new identification sign.
CHE - WC II	06-Aug-24	Operational	has tree stand belonging to ODFW.
CHE - Yamsey	01-Aug-24	Operational	Yamsey is now functional. I was able to clear the line, however I will improve the flow when the yellowjackets subside. 20" of water in the drinker 24" in the tank. It's a self leveling system and the tank should hold nearly 36".
CHQ - 01	25-Sep-24	Nonoperational	Took measurements for a new gutter. Hope to replace it before winter begins. The drinkers were empty. The apron is in bad shape but may be fixable by flipping the sheets and aligning the rafters.
CHQ - 02	29-Aug-24	Operational	
CHQ - 03	06-Sep-24	Operational	Rainmaker Drinker Full, No salt present , I left 50#, repaired apron, secured screen and metal cover. Light usage except birds.
CHQ - 04	28-Oct-24	Operational	
CHQ - 05	10-Jun-23	Operational	This was our first visit since the area was reopened from the Bootleg fire. Fire came extremely close but appereared to went around. Needs salt, No way to measure the tank as no hole was left after the rebuild 3 years ago. It appears the drinker was flowing but unable to verify. Bird house was still in good shape.
CHQ - 06	01-Aug-24	Operational	
CHQ - 07	06-Nov-24	Operational	Deer stand still there
CHQ - 08	01-Aug-24	Operational	
CHQ - 09	01-Aug-24	Operational	added new salt block
CHQ - 12	01-Aug-24	Operational	
CHQ - 13	24-Aug-22	Nonoperational	is a nonoperational single apron that is down a road that I can only describe as ATV ONLY as it will trash any truck and likely pop tires, so be prepared. I spent 3 days straight cutting my way through about 2 miles of trees across this road. From where I stopped, the guzzler is still another ¼ mile through the woods until you reach the guzzler. There is a LOT of game activity along this guzzler, a large bear has tried to dig it out, but hasn't damaged it. The float box is roughly 50 yards to the southeast of the apron. I have dug up the float box, but there is an obstruction in the line from the tank to the box that I can only hope can be cleared by compressed air. The lines to one of the drinkers are clear, the other has been disconnected.

CHQ - 14	18-Aug-22	Operational	An apron style guzzler with two aprons forming an L shape to a single gutter. The road is pretty well choked with manzanita, so there will be some pinstriping for sure. I cleared it enough to get a truck down down to it. I cleaned off the apron, dug up the float box, snaked the pipes, disassembled/cleaned/reassembled the float mechanism, as well as unburied the drinker. No critter sign as it was nonoperation for a time. Needs salt.
CHQ - 15	09-Dec-22	Operational	
CHQ - 17	06-Nov-24	Operational	Need to anchor gutter box and re-level the apron.
CHQ - 18	23-Sep-24	Operational	The north drinker had water but the south drinker was empty. The old snow dam was not long enough for the new drinker so I will need to get another 2 x 6 x 10 pressure treated board and install it for the snow dam.
CHQ - 19	23-Sep-24	Operational	The drinker was again empty when I arrived. I use air pressure to clear the line. Got a good water flow so hopefully it stays that way. It seems to be a recurring problem and the only fix may be to pull the apron and open the tank to remove whatever is plugging the system.
CHQ - 21	28-Oct-24	Nonoperational	Destroyed in the Copperfield Fire
CHQ - 22	06-Nov-24	Operational	
CHQ - 25	29-Aug-24	Operational	water added and maintained by hunters. Has a permanent tree stand, blew out one drinker the other was ok.
CHQ - 26	29-Aug-24	Nonoperational	Apron in Poor shape, needs one 8' standard sheet metal and considerable repair, and one 2x6 replaced. No water in drinkers. We did not dig up the float valve.
CHQ - 27	03-Oct-24	Limited	The gutter needs to be replaced one end broken off and the bottom of the gutter has been pushed down due to snow load to below the tank input. Water will drain out of the end before it gets high enough to flow into the tanks. It will work in a limited capacity until the water is used up.
CHQ - 31	09-Dec-22	Operational	
CHQ - 32	10-Jun-23	Operational	51 inches of water, needs salt and fence repaired. Squirrel screen was missing and needs replaced.

CHQ - 35	25-Sep-24	Limited	Even though the tanks were overflowing the drinker only had about 2 inches of water. I snaked the line but couldn't get water to flow. I dug up the feed line at the tank and pulled one of the feed lines and water gushed out. I then snaked the line backwards with the water flowing and still could not get water to flow. I pulled the snake completely through the line, there was no blockage. I am at a loss to explain why the drinker didn't fill.
CHQ - 37	03-Oct-24	Operational	Lots of deer tracks. We were not able to drive up to guzzler so we were unable to clean the drinker or apron. Tanks were full but the drinker was only half full.
CHQ - 38	25-Sep-24	Operational	The apron is sagging but is still working. Should be repaired soon.
CHQ - 39	03-Oct-24	Operational	We were able to x-country to guzzler. Need to clean bitterbrush away from the tanks. lots of deer tracks.
CHQ - 40	23-Sep-24	Operational	I could not believe how much stuff was in the drinker seeing that I just cleaned it out 3 months ago. I must have shoveled out 8 full scoops of dirt and pine needles.
CHQ - 41	06-Nov-24	Operational	
CHQ - 42	01-Nov-23	Operational	Guzzler replaced with boss tank with a new apron and drinker after it was destroyed in fire
CHQ - 46	09-Dec-22	Nonoperational	
CHQ - 50	03-Oct-24	Operational	We were not able to drive up to guzzler so we were unable to clean the drinker or apron.
CHQ - 51	09-Dec-22	Operational	
CR16	09-Dec-22	Operational	
CR17	09-Dec-22	Operational	
CR19	09-Dec-22	Operational	
CR20	09-Dec-22	Operational	
CR21A	27-Sep-23	Operational	Apron to a Rainmaker tank drinker. This was placed by someone, I assume the Forest Service if it wasn't one of our volunteers. Water level is high, but the system is definitely functional. Cleared the apron and filled in badger holes, of which there were many. High game traffic area, could use a game camera, but there were signs of deer, elk, bear, badgers and birds. I've attached a picture of this guzzler
CR22	27-Sep-23	Operational	Single Apron with float box. Cleaned out and repaired float box; reburied it and placed a small dead tree stump upright over it. Might need a new float assembly eventually, but it works. Dug out drinkers and cleared pipes. Placed 25# salt.
CR31	09-Dec-22	Operational	
CR37	09-Dec-22	Operational	

CR38	09-Dec-22	Operational	
KLA - 03	05-Aug-23	Operational	
KLA - 04	22-Aug-24	Operational	Installed new rainmaker floatvalve,drinker. One tank still plugged up. We're working on it
KLA - 05	05-Aug-23	Operational	
KLA - 07	26-Jun-24	Operational	downspout was clogged with needles 10% salt remaining and 1/2 block added
KLA - 08	05-Aug-23	Operational	
KLA - 09	05-Aug-23	Operational	
KLA - 16	18-Jul-24	Operational	Apron can use fall adjustment
KLA - 49	13-Jul-23	Operational	
SIL - FS 01	19-Oct-24	Operational	installed new rainmaker float valve/drinker. Has two large above ground tanks.
SIL - FS 02	19-Oct-24	Operational	dug up and found break in outlet pipe. Repaired. Hopefully will hold water this winter. Has two large above ground tanks
SOU - Bear Flat	05-Aug-23	Operational	
SOU - Big Fir	19-May-24	Operational	Installed a new Rainmaker floatbox drinker Left 23# salt
SOU - Bly Mtn	05-Oct-24	Nonoperational	Plugged up! Float box not located but 24" hole dug by someone below the post. 2 concrete drinkers, dry. Apron ok. No measure of water Couple of trees over fence.
SOU - Chicken Hills 1	12-Sep-24	Operational	
SOU - Chicken Hills 2	13-Aug-24	Operational	No salt, put out 10#
SOU - Ezel	23-Jul-24	Operational	
SOU - Fox Lake	23-Jul-24	Operational	
SOU - Granada Butte	12-Sep-24	Operational	
SOU - Harpold Ridge	05-Aug-24	Operational	I added 4 T posts and re strung wire. It is now cow proof I hope.
SOU - Hayden Mtn	05-Aug-23	Operational	
SOU - LKHILL BIRD	21-Nov-23	Operational	According to Craig from BLM....Small self contained unit designed for upland game birds. Must walk in from parking lot.
SOU - LKHILL EAST	21-Nov-23	Nonoperational	According to Craig from BLM. ...traditional style with metal apron, float box and sheep tank. Water in underground tank, none in drinker. Access denied by landowner. Must hike in. I'll try to get road access,
SOU - OSF 01	12-Sep-24	Operational	
SOU - OSF 02	12-Sep-24	Operational	
SOU - Parker Mt	05-Aug-23	Operational	
SOU - Swan Lake Rim	05-Aug-23	Operational	
SOU - Ward Road	05-Aug-23	Operational	

SUN - ODF 1	08-Nov-22	Operational	
SUN - ODF 2	09-Dec-22	Nonoperational	
SUN - ODF 3	09-Dec-22	Operational	
Yainax 01	05-Nov-24	Operational	
Yainax 02	05-Oct-24	Operational	